ORDER To be used for FORM Cash Transactions only

DUPLICATE

Copyright of the Motor Agents Association Ltd.

		Ltd.
I/We hereby agree to purchase from you DITIONS HEREOF (including those printed cextras and accessories, hereinafter called the go	(hereinafter described as the "Seller") SUBJECT TO THE TERMS AND CON- poverleaf) the undermentioned vehicle, pods:	FOR OFFICE USE ONLY Chassis No
DESCRIPTION OF VEHICLE Make MAKES Colour DESCRIPTION OF VEHICLE MAKE MAKES Upholstery BEST & CAC MANUFACTURER'S OPTIONAL EXTRAS including Purchase Tax	Number Plates Delivery Charges	£ s. d.
ACCESSORIES EXTRAS — Insurance	Dal :	
Licence: From	to	
STIMATED DELIVERY DATE EDUCT: Allowance (Subject to Condition 7) for conforms to the following description: Make c.c. T.	Used Motor Vehicle which I/We certify	AL H PRICE 3
Chassis No. Er	egistered No.	918
Licensed to Da	ear of make	
	Purchase YES/NO DD: Hire Purchase Balance outstanding any) under Condition 7(b), as tified by H.P. Co. concerned.	
NOTE. This final balance should be completed o when settlement figure, if any, is known.	ADD: H.P. Balance outsta	

I/WE ACKNOWLEDGE that I/We have not been induced to enter into this transaction by any representation as to quality, fitness for any purpose, performance or otherwise of the goods other than the representation contained (if the goods be new) in the Manufacturer's or Concessionaire's Price List or Specification for which representations the Seller is, subject to Condition 3 (b) overleaf, not responsible or (if the goods be not new), in any written Specification prepared by the Seller and annexed to this Form.

AND I/WE FURTHER AGREE to deposit the sum of

f......forthwith and to pay the balance (see Clause 9) as soon as the goods have been completed for delivery and notification thereof given to me/us by post at the following

I certify that I am 21 years of age or over (where the Purchaser is an individual).

This document contains the terms of a contract. Sign it only if you wish to be legally bound by them.

Signature

Address

·				
		MARCOS 1	500	
	CHASSIS NO. SENGINE NO.	 5	DELIVERY DATE WE 16 9 66	
***************************************	EXTERIOR COLOUR	Necescalive	OPTIONAL EXTRAS:	
	TRIM COLOUR	Risek	RADIO	
	R.H.D./L.H.D.		SEAT BELTS	
	LIGHTING SPEC.	UK	magnesium wheels	
	FACTORY BUILT	specific section of the section of t	FOG LAMPS	
a t	COMPONENT FORM	YES	BRAKE SERVO	
	ENGINE		REVERSE LAMPS	
•	GEARBOX	*	CIBIE Q.I.V. HEADLAMPS	
	REAR AXLE		MASERATI AIR HORNS	
			SUP. SEAT CUSHION	

TIL-STANDARD EXTRAS:

8th November, 1967.

Mr. Riwin Holden, "Far View." 21 Catholic Lane, Sedglay, Staffs.

Dear Mr. Holden,

Thank you for your letter of the 3rd November and I would confirm that I have already heard from Mr. Copp. I would like to thank you very much for lending your car to him for the performance car show and I would confirm that under the terms of our Exhibition Covenant with the S.M.M.T., we are not allowed to exhibit new unused cars at any other show throughout the year other than those organised by our officially appointed dealers.

When you decide to purchase a Marcos 1600 or Mini-Marcos, perhaps you would give me a ring when we can sort out suitable terms.

Yours sincerely, for MARCOS CARS LIMITED

W.N.R. HARRISON

WNRH/HJF.

2nd November, 1967.

Mr. Edwin Holden, wrar View? El Catholie Lane, Sedgley, Staffs.

Dear Mr. Holden,

Thank you for your letter just received and I am naturally delighted to hear that your 1500 has been going so well. To be perfectly frank, I would not expect any trouble with the paintwork or glassfibre on the car but would think that this must have been caused by stones flying up underneath the bodywork. Are the splits and cracks in the glassfibre on top of the wheel arches? If they are, they will be your liability but if they are anywhere else, the ball would be in our court and although the car is out of warranty, I will have them put right F.O.C. when you are next in this district.

I was also very pleased to hear that you are changing the car for a 1600 version this summer. The 1650 c.c. Lawrencetune powered version has been discontinued sometime ago and we now have the 1600 on offer powered by the Ford 1600 cross-flow power unit which, as you know, has only been on the market for a very short time. To perperfectly frank, I find this infinitely superior to the Lawrencetune version and of course, it is covered by full Ford warranty.

This is available ex works in component form at £1485 and less sunroof at £1465. Minilite magnesium wheels are available at £98 ex works, giving a grand total of £1563. There is tremendous demand for good used Marcos cars and yours could be sold at a very competitive price. In this case, I could do a deal with you direct and if you are interested in this, perhaps you would drop me a line when we could work out a suitable price and delivery date.

As regards the purchase of a Mini-Marcos body/chassis unit, I am attaching a brochure on this car and I would suggest it is purchased in Stage V form. The great majority of the pard skilled work has then been carried and all one has to do is transfer the Mini components on the van into the shell to give a very attractive little car.

Perhaps you would think these things over and drop me a line as soon as possible and I am delighted to tell you that business is really booming down here - we have taken so many orders at the Motor Show, we really do not know what to do and now the fun starts trying to find out how to make them even quicker.

Yours sincerely, for MARCOS CARS LIMITED

W.RNR.HARRISON

TERNOLOGIA BERNARIAN AND LARGE SANCTON DE L'ANDRE SENTENCIA DE L'ANDRE L'ANDRE AND MARIE AND MARIE AND MARIE A REAR REAR DE L'ANDRE L'ANDRE RESERVE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L'ANDRE L

WARN HJF.



WNRH/GSW

Foley Park Motors, Stour ort Road, Kidderminster.

6th October 1966

Dear Sire,

MARCOS 1500 - AR HOLDEN

Many thanks for the warranty claim covaring certain work on the above car. Whilst weare most grateful to you for carrying out the above repairs in future will you please ring me personally before starting any such work; we can then discuss in detail the points raised.

Referring to your present claim there are one or two queries:

- Where is the original faulty fuel gazge?
- 2. Am incorrect type of replacement gauge has been fitted where did you obtain
 - The n/s top dash board fixing screw was badly damaged was this like this when you received the car?
 - 4. The dash board has been badly chipped whose liability?
 - 5. I notice you padded the boot like lip this simply lifted the lid and as the customer has complained we have had to relit it.
 - The bonnet was damaged in two places I presume this was caused by an incorrectly fitted radiator due to a production error?
 - 7. What was the cause of the steering column creak?

I would be grateful if you would let me have the above details as soon as possible, as action may well have to be taken in the production department to prevent any future recurrence of these troubles.

Yours faithfully,

W.N.R.Harrison.

PECK. Dealer Requesting Credit Foley Park Motors. Stourport Rd., kidderminster. Date of Repair ... 29.9.66 Name and Address of Owner Mr. dolden, 21 Catholic Lane, sed**gley** Staffs. Date of Sale ... 16. 9.66. Warranty Engine No. Mileage Chassis No. Model 3577 5015 452 1500 Material Claim Invoice No. Part Name Distributor Concession Quantity Part No. Fuel gauge Dip switch LABOUR CLAIM Hours Description of Labour Operations Remove dush board, fit new fuel gauge 9 hours Remove column surround, fit new Vendor Dealer if retail Remove boot latchy modify latch and Labour is claimed refit. Refit steering column bracket Describe fully actual Faults or Defects and reasons for claim, Fuel gauge faulty, dip switch not working, boot lid bad rettles. Steering) column creaking Date 30-9.66. Signature Distributor or Dealer

Original and one copy of this form to be forwarded to the above address, together with displaced material.

f, to low varanty rate aggestable

Dindscreen wipers

Dindscreen washer

does not wark

Full garge inacvirate

Boot lid not fit

properly also doors.

Window hold fullen

off, drivers side.

Rubber off the footole

broke.

Touch up Paintwork

26th September, 1966.

Dear Mr. Holden ,

Marcos 1500 - Chaseis 5015

Now that you have taken delivery of your new Marcos 1500 we would remind you that one of the conditions of the 12 month/12000 mile warranty is that your car is returned to the works for a 500 mile service; this is a really comprehensive check and is carried out on an entirely free of charge basis.

Will you therfore please telephone me as soon as possible to arrange a mutually convenient date for this service to be undertaken.

Yours sincerely,

W.N.R. HARRISON

ADVICE NOTE

№ 1440



MARCOS CARS LTD

	ToMr. Edwin Holden,			
	Far View,			
	21 Catholie Lane, Sedgley, Nr. Dudley,	Date	13.9.6	6.
,1966				
Sept.	To supplying:			
	One Marcos 1500 Body Cassis Unit Mo- Colour: Norwich blue with bi upholstery	5015 Lack	2775	-
	DELLYEU :		_15	-
			£790	•
\				

1394 C

Date

To:

its. Shekn Holden

The sempelityings

E. & O. E.

1966

23

MARCOS CARS COMPONENTS LTD

GREENLAND MILLS, BRADFORD-ON-AVON, WILTSHIRE

Telephone: BRADFORD-ON-AVON 2102, 2279

7th September, 1966.

Mr. Edwin Holden, Far View, 21 Catholic Lane, Sedgley, Nr. Dudley.

Sudae Šala relato, casa supu n

Dear Mr. Holden,

Thank you very mick indeed for your communication of the 4th September.
We are, of course, very pleased to hear that you have now ordered a
Marcos 1500 through Messrs. Foley Park Motors, Kidderminster. With
regard to your various queries, we would answer as follows:-

The vehicle you have on order is in component form and as such will be delivered to you in the following manner:-

- a) Body Chassis Unit completely assembled, i.e. fully trimmed, instrumented, with rear axle in position, etc.
- b) Engine/gearbox assembly fully built up.
- c) Front suspension wishbone assemblies fully built up, only requiring to be attached to chassis by 8 bolts.
- d) Radiator complete with hoses.
- e) Exhaust system consisting of three items, i.e. exhaust manifold, flexible coupling piece and silencer system.
- f) 5 road wheels and tyres.

All bolts/nuts, washers, etc. are in position on chassis ready to receive attachments. Loose nuts and bolts etc. are not required or supplied. As mentioned to you previously, we consider that an individual with limited knowledge can assemble the component vehicle in 8/10 hours, 2 or 3 persons in considerably less time.

We would mention at this time that we recommend owners who have constructed their own vehicles to return them to the works for a thorough check over and service after the completion of 500 miles. This involves no cost to the customer whatsoever, being part of our after-sales service.

With regard to the glass-fibre body work, it is, of course, fully proofed against all weather conditions and, of course, is fully rust proofed. The finish of the exterior body panels is in no way inferior when compared with normal tin motor cars. On the contrary, a glass-fibre body will remain completely rust free, its life span being incalculable.

Lastly, regarding your request for building tips, we cannot, unfortunately, supply you with any details which will help you to assemble your vehicle. It is a condition laid down by H.M. Customs & Excise Authorities that manufacturers of component vehicles on no account supply the purchaser of such a vehicle with assembly instructions. However, as mentioned above, the assembly of a vehicle is straightforward, it being our opinion that it would be quite impossible for the car to be wrongly assembled. However, we do request that we see a completed vehicle on the completion of 500 miles so that we may fully check its construction. It is a condition of our warranty that the vehicle be returned to us for this free service.

We sincerely hope that we have answered all your points fully and should you have any further queries, please do not hesitate to contact the writer. We will do our very utmost to get your vehicle to you at the earliest opportunity. Due to non deliveries of various parts from suppliers, we are, unfortunately, at this time, running some 3/4 weeks behind schedule. However, the situation is improving daily and we hope to be in a position to contact Foley Park Motors within the next week or so, giving the actual delivery date of your vehicle.

Please do not hesitate to contact us should you have any further queries.

Yours sincerely, for MARCOS CARS LIMITED

> JOSEPH A. BYERLEY General Manager

JAB/HJF.

ORDER

H. Pocknell

Foley Park Motors, Kidderminster

LEYLAND · TRIUMPH · ROOTES

Midlands Distributors for RAMBLER PONTIAC MARCOS

3rd August, 1966.

Marcos Cars Ltd., Greenland Mills, Bradford-on-Avon, Wilts.



Please Supply:

One Marcos 1500 finished in Norwich Blue with black trim and complete to makers latest specification.

Delivery loth September, 1966, as per telephone.

for Foley Park Motors

8

M. Pocknell

19th May, 1966.

Mr. E. Holden, Far View, 21 Catholic Lane, Sedgley, Nr. Dudley.

Dear Mr. Holden,

We thank you very much indeed for your letter of the 17th May and have much pleasure in enclosing details of the new Marcos 1500 officially announced on 2nd May, 1966. As you will see from the attached pries release, the price of the 1800 Volvo model has indeed been increased by some £335 due mainly to the continued import surcharge and rising costs.

With regard to the power output of the Ford unit fitted to the 1500 model, out stated output is 85 b.h.p. at 5,300 - this figure is the minimum to be expected. As you will no doubt appreciate individual engines can produce slightly more or slightly less. We have, in fact, stated the lowest possible b.h.p. output. The engine is completely standard apart from the fitting of twin Stromberg 150 CD Carburetters and a full flow exhaust system.

Performance figures again can vary - according to driver, weather conditions stc. However, the average figures we have recorded are as follows: 0 - 50 6.5 secs; 0 - 70 11.2 secs; 0 - 100 27 secs.

With regard to the external styling of the new 1500, this remains unchanged. However, the interior has been improved to the extent that little more room for passenger comfort has been obtained. The dashboard facia new incorporates a polished walnut burr finish.

As regards the time taken to assemble a component vehicle, this again depends on the mechanical knowledge of the individual concerned. However, a person with some limited knowledge can assemble the very few components in a matter of 8 - 10 hours.

If we can be of any further assistance to you here at the factory, please do not hesitate to contact us.

Yours sincerely, for MARCOS CARS LIMITED

JOSEPH A. BYERLEY
Sales Executive

JAB/HJF.



№ 1099 S

MARCOS CARS LTD

	To Foley Park Motors, Kidderminster, Worcs,					
		Date	13.9.66.			
1966						
Sept.	To supplying:					
	One new Marcos 1500 Body Chassis Unit No. 5015 Engine No. K3577					
	Colour: Norwich blue with black upholstery		£1,295			
	Less 13 ¹ /8%	. delication of the second	170			
		a consideration of the constant of the constan	£1,125			
	DELIVERY :		15			
		A son a son representation	£1,140			
		And the second s				
X						

GREENLAND MILLS, BRADFORD-ON-AVON, WILTS, Tel: BRADFORD-ON-AVON 2279

102406

11th March, 1966.

We thank you for your recent communication regarding our Marcos 1800 models. In reply to your query, we would advise you that the delivery we are now quoting on receipt of order is approximately 12/15 weeks; and if you should care to take delivery of a vehicle in September, 1966, we would advise you to place your order by the end of June at the latest.

If we can be of any further assistance to you, please do not hesitate to contact the writer.

Yours faithfully, for MARCOS CARS LIMITED

JAB/HJF.

Mr. Edwin Holden,

21 Catholic Lane,

Far View,

Sedgley. Nr. Dudley.

Dear Sir,

JOSEPH A. HYERLEY Sales Executive